



04-Jan-2009



02-Jul-2009

Photos of watercress before and after natural die-back in late spring to early summer as an illustration of annual vegetation changes in lower river channel. Location of photos is on the Ventura River near Casitas Springs. The photos are of the same location taken at two different times.

Scott D. Lewis
Fisheries Program Manager
Casitas Municipal Water District